

[illegible]

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 589	Date: 09/03/2008	Basin: LL - 44	Manhole ID: S19I__010MH
Defect No: OB01	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: 4 S. PAYSON ST.			

Source Type: 01 Main Sewer

Sector: 01 Public

Location: 12 Alley

Severity: 03 Moderate

Drainage Area: 200

Comments: SMOKE IS COMING FROM THE MIDDLE OF THE ALLEY ALONG MAIN SEWER LINE. DEFECT IS BEHIND ADDRESS.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01
Filename: 1029-589_OB01-01.jpg

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 589	Date: 09/03/2008	Basin: LL - 44	Manhole ID: S19I__010MH
Defect No: OB02	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: 14 S. PAYSON ST.			
Source Type: 02 Service Line		Sector: 02 Private	
Location: 08 Yard - Back		Severity: 03 Moderate	Drainage Area: 30
Comments: SMOKE IS COMING FROM GROUND IN MULTIPLE PLACES ALONG YARD SIDE BELOW FENCE.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-01
Filename: 1029-589_OB02-01.jpg

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 589	Date: 09/03/2008	Basin: LL - 44	Manhole ID: S19I__010MH
Defect No: OB03	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: 16 S. PAYSON ST.			
Source Type: 02 Service Line		Sector: 02 Private	
Location: 08 Yard - Back		Severity: 03 Moderate	Drainage Area: 30
Comments: SMOKE IS COMING FROM GROUND IN MULTIPLE PLACES ALONG YARD SIDE.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB03-01
Filename: 1029-589_OB03-01.jpg